
Pedestrian Bridge Inspection

Project Location



Scope of Work

- . Inspect 15 pedestrian bridges
- Structurally analyze bridge in worst condition
- . Create a geodatabase

Challenges

- Winter conditions
- . Not all bridges had load ratings
- As-built documents were not available
- Template and guide were designed for non-engineering users

Dream Team

Samantha Caldwell, Shelley Giraldo, Jared Kinney and Brian Weigand



Pedestrian Bridge Inspection Template

×	MOAProjectB	
	General Information	
Report Number *		
Survey Bridge Area * Take a GPS point at the center of the bridge		
61°11'N 149°50'W ± 121.37	3 m	\Diamond
© Esri contributors	Seawolt DT Alaska-Anchorage	y Dr
Weather *		
Temperature *		
Today's Date *		
Date		~
Structure Name *		
Trail Name *		

Capabilities

- ESRI server

Geodatabase

- . Coded in Python
- . Cloud-based located on ESRI server
- . Automatically updates to comply with federal standards

Capabilities

- . Downloads data collected by the MOA Project B App
- . Creates a visual representation of the data
- . Queries data to identify bridges that meet specific criteria
- . Can be simultaneously edited by multiple users

	hester Cret	Margaret Eg Sullivan Pa		9th Avenue		West 18th Avenue		Nex 19th Avenue Nex 19th Avenue Numa Valley o The Moc Park	West 20th Avenu	e Station of the second	Charles W Smith Memorial Park in, USGS, METI/NASA, EF	PA, USDA CSIL
surveyPoint (4 fea	atures, 0 selected)											Options 🔻
What is Today Date	Report Number	Weather	Temperature	Structure Name	Trail Name	Park Name	Inspector 1	Inspector 2	Bridge Type	Type Of Utilities	Surface Material (Approach 1)	Surface Conc (Approach 1)
Feb 25,2017	5	Cold	19	Spenard Rd, Spur Bridge	Chester Creek	Westchester Lagoon	Brian Weiganx		В	Yes, unknown but under the bridge	Asphalt	Other
Feb 25,2017	6	Snowing	20	Bunker Street Bridge	Chester Creek	Valley of the Moon	Brian Weigand		A	Under right side of bridge	Asphalt	Smooth
Feb 25,2017	7	22	22	Valley of moon			Brian weigand		A	A lot under bridge	Asphalt	Smooth
Feb 25,2017	8	Sunny	22	West 19th Bridge	Chester Creek	C Street COmmunity Garden	Brian WEigand		A	None	Asphalt	Smooth


MOA Project B App

. Coded in Visual Basic . Customized Survey 123 App . Can be used on any iOS or Android device . Accompanied by MOA Pedestrian Bridge Guide

. Taken into the field to gather inspection data and assess bridge conditions

. Capable of directly submitting collected data to

. Can integrate with any other mapping program, such as Google earth, Civil 3D or MicroStation



compliant . Overall ratings indicated that bridges are in acceptable condition

Tikishla Park Bridge



. Full structural analysis was performed . Bridge is adequate for normal pedestrian use but cannot support 90 psf pedestrian load required by current AASHTO standards

motor vehicles should be installed

. H-5 design vehicle should not cross bridge . Removable bollards and signs prohibiting . Railing should be replaced

. Anchorage Parks and Recreation/Josh Durand . UAA School of Engineering/Dr. Abaza



Inspection Results

. Most bridge railings are not AASHTO LRFD

. Bridges should be reinspected in summer



Acknowledgements